

Current Open Issues

Issue ID	Title	Location	Type	Priority	Assigned To	Created
16	Hand basin tap	Room 079	Plumbing Fittings	Critical		2026-02-09
25	Hand basin	Room 076	Plumbing Fittings	Critical		2026-02-10
37	Extractor fan in bathroom	Room 006	Elec General	Critical		2026-02-19
71	Painting a stain on the ceilin...	Room 336	Painting	Critical		2026-02-26
73	Shower tap	Room 099	Plumbing Fittings	Critical		2026-02-26
79	Bathroom mirror	Room 073	Fixtures	Critical		2026-03-01
31	Broken window	Room 441	Fixtures	High		2026-02-13
41	Extractor fan	Room 055	Elec General	High		2026-02-20
76	Toilet	Room 007	Plumbing Fittings	High		2026-02-27
77	Bathroom ceiling	Room 077	Painting	High		2026-02-27
78	Shower trap	Room 074	Plumbing Fittings	High		2026-02-27
44	Skirting to be varnished	Room 015	Fixtures	Normal		2026-02-23
46	Hole in ceiling/ skirting edge...	Room 015	Painting	Normal		2026-02-23
47	Bathroom frame fixings	Room 015	Fixtures	Normal		2026-02-23
52	Switches and wall sockets	Room 016	Painting	Normal		2026-02-23
53	Remove coat hook behind door	Room 016	Fixtures	Normal		2026-02-23
55	Yucca jacaranda bridge light c...	Yucca Passages	Elec Lighting	Normal		2026-02-23
57	Skirting fixings filled and fi...	Room 055	Fixtures	Normal		2026-02-23
58	Wall lights	Room 055	Painting	Normal		2026-02-23

59	Wall cover covers	Room 055	Elec General	Normal	2026-02-23
60	Remove coat hanger	Room 055	Fixtures	Normal	2026-02-23
28	Leak Emmanuals roof	Emmanuals	Buildings	Low	2026-02-12
68	Malawi chairs painting	General Task	Painting	Low	2026-02-25
